

Safety Data Sheet ClearFlo-pH-SA-D 50%

SECTION 1: Identification of the substance/mixture and of the company/undertaking

1.1 Product Identifier

Product name ClearFlo-pH-SA-D 50%

Synonyms; trade names Concentrated sulphuric acid, Oil of vitriol, Sulphuric acid,

Battery acid

REACH registration number 01-2119458838-20

CAS number 7664-93-9 **EC number** 231-639-5

1.2. Relevant Identified uses of the substance or mixture and uses advised against

Identified Uses Treatment of drinking water, has received approval by the

European Committee for Standardisation. Manufacture of substances. Intermediate Processing aid pH regulating agent Battery electrolyte Pharmaceutical substance Plating and metal surface treatment agents Flue gas scrubber.

and metal surface treatment agents Flue gas scrubber

Laboratory agent.

1.3. Details of the supplier of the safety data sheet

Supplier GPC Clear Solutions Limited,

Unit 57 Riverside Estate,

Sir Thomas Longley Road, Medway City Estate,

Rochester Kent ME2 4DP

Tel: 01634 326920 Fax: 01634 570469

Sales@gpcclearsolutions.co.uk

1.4. Emergency telephone number

Emergency telephone 01634 326920 (Office hours only)

SECTION 2: Hazards Identification

2.1. Classification of the substance or mixture

Classification (EC 1272/2008)

Physical hazards Not classified

Health hazards Skin Corr. 1A - H314

Environmental hazards Not classified

Classification (67/548/EEC or

Revision Date: 22/09/2016

1999/45/EC)

Human health The IARC had issued the following statement (Monograph

100F): "There is sufficient evidence in humans for the carcinogenicity of mists from strong inorganic acids. Mists from strong inorganic acids cause cancer of the larynx. There is limited evidence for a causal association of mists from strong inorganic acids with cancer of the lung. Mists from strong inorganic acids are carcinogenic to humans

(Group 1).

ClearFlo-pH-SA-D 50%

2.2 Label elements

EC number Pictogram

231-639-5



Signal word

Hazard statements

Precautionary statements

Danger

H314 Causes severe skin burns and eye damage.

P260 Do not breathe vapour/spray.

P264 Wash contaminated skin thoroughly after handling. P280 Wear protective gloves/ protective clothing/ eye

protection / face protection.

P301+P330+P331 IF SWALLOWED: Rinse mouth. Do

NOT induce vomiting.

P303+P361+P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with

water/shower.

P304+P340 IF INHALED: Remove person to fresh air and

keep comfortable for breathing.

P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if

present and easy to do. Continue rinsing.

P310 Immediately call a POISON CENTRE/ doctor.

P321 Specific treatment (see medical advice on this label).

P363 Wash contaminated clothing before reuse.

P405 Store locked up.

P501 Dispose of contents/ container in accordance with

national regulations.

Sulphuric Acid

Contains

 $Supplementary\ precautionary$

statements

P260 Do not breathe vapour/ spray.

P264 Wash contaminated skin thoroughly after handling. P301+P330+P331 IF SWALLOWED: Rinse mouth. Do

NOT induce vomiting.

P304+P340 IF INHALED: Remove person to fresh air and

keep comfortable for breathing.

P310 Immediately call a POISON CENTRE/ doctor. P363 Wash contaminated clothing before reuse.

2.3. Other hazards

2 | Page

ClearFlo-pH-SA-D 50%

SECTION 3: Composition/Information on Ingredients

3.2. Mixtures

ClearFlo-pH-SA-D 50%	30-80%
CAS number:	
Classification	Classification (67/548/EEC or 1999/45/EC)
Skin Corr. 1A - H314	C;R35

The Full Text for all R-Phrases and Hazard Statements are Displayed in Section 16.

SECTION 4: First aid measures

4.1. Description of first aid measures

General Information Speed is essential! Get medical attention immediately. **Inhalation** Remove affected person from source of contamination.

Give oxygen if necessary. Apply artificial respiration if breathing has ceased or is failing. Do not use mouth-to-mouth resuscitation if victim ingested or inhaled the

substance.

Ingestion If confined to the mouth, rinse mouth thoroughly and

ensure water is not swallowed. If swallowed, drink plenty of water. If substance has been swallowed, give water to

drink immediately Do not induce vomiting.

Skin Contact Remove contaminated clothing and rinse skin thoroughly

with water.

Eye Contact Rinse immediately with plenty of water. Remove any

contact lenses and open eyelids wide apart. Continue to

rinse for at least 15 minutes.

4.3. Indication of any Immediate medical attention and special treatment needed

Notes for the doctor After treatment keep patient under observation for 48

hours, as delayed pulmonary oedema may develop.

SECTION 5: Fire fighting measures

5.1. Extinguishing media

Suitable extinguishing media Use fire-extinguishing media suitable for the surrounding

fire. Use water to cool containers.

5.2. Special hazard arising from the substance or mixture

Special hazards Oxidising agent. Thermal decomposition or combustion

products may include the following substances: Toxic

gases or vapours.

ClearFlo-pH-SA-D 50%

5.3. Advice for fire fighters Special protective equipment

for fire fighters

Wear positive-pressure self-contained breathing apparatus

(SCBA) and appropriate clothing.

SECTION 6: Accidental release measures

6.1. Personal precautions, protective equipment and emergency procedures

Personal precautions Wear protective clothing as described in Section 8 of this

safety data sheet.

6.2. Environmental precautions

Environmental precautions Do not discharge into drains or watercourses or onto the

ground. Avoid discharge onto drains. Spillages or

uncontrolled discharges into watercourses must be reported

immediately to the Environmental Agency or other

appropriate regulatory body.

6.3. Methods and material for containment and cleaning up

Methods for cleaning up Small spillages: Absorb spillages with non-combustible,

absorbent material. Do not use sawdust or other

combustible material. Flush contaminated area with plenty of water. Large spillages: Neutralise spilled material with crushed limestone, slaked lime (calcium hydroxide), soda ash (sodium carbonate) or sodium bicarbonate. Flush contaminated area with plenty of water. Collect and place in suitable waste disposal containers and seal securely.

Extensive fumes may be released.

6.4. Reference to other sections

SECTION 7: Handling and storage

7.1. Precautions for safe handling

Usage precautions Wear appropriate protective clothing. Provide adequate

ventilation. Avoid inhalation of vapours. Use approved respirator if air contamination is above an acceptable level. Avoid contact with skin and eyes. Never add water to sulphuric acid. Dilute by slowly adding acid to water, with stirring. Keep away from metals, organics, nitrates, chlorates, carbides and hot surfaces, as corrosive and toxic

decomposition products can be formed.

7.2. Conditions for safe storage, including any incompatibilities

Storage precautions Store in a cool and well-ventilated place. Store in vessels of

mild steel. Note that dilution below 70% will allow ClearFlo-pH-SA-D to attack steel. Suitable containers: Plastic. Stainless steel. Store away from the following materials: Alkalis. Caustic products. Strong oxidising

agents.

7.3. Specific end use(s)

ClearFlo-pH-SA-D 50%

SECTION 8: Exposure Controls/ Personal protection

8.1. Control parameters

Occupational exposure limits

Sulphuric acid

Long-term exposure limit (8-hor TWA): 0.05 mg/m³

8.2. Exposure controls Protection equipment











Appropriate engineering

controls Provide adequate general and local exhaust

ventilation. Observe any occupational exposure

limits for the product or ingredients.

Use protective gloves. Rubber or plastic.

Eye/face protection The following protection should be worn: Chemical splash

goggles or face shield.

Hand protection

Other skin and body

protection Chemical suit and boots if handling large quantities.

Respiratory protection If ventilation is inadequate, suitable respiratory protection

must be worn.

SECTION 9: Physical and Chemical Properties

9.1. Information on basic physical and chemical properties

AppearanceClear Liquid.ColourColourless.OdourOdourless.

pH (concentrated solution): <0.1

Melting point -1°C For 96% concentration.

Initial boiling point and range

Relative density pH (concentrated solution): <0.1

-1°C For 96% concentration.

323°C @ For 96% concentration.

1840 @ 20°C For 96% concentration.

Solubility(ies) Soluble in water.

9.2. Other Information

SECTION 10: Stability and reactivity

10.1. Reactivity

10.2. Chemical stability

Stability Stable at normal ambient temperatures and when used as

recommended.

10.3. Possibility of hazardous reactions

Possibility of hazardous

ClearFlo-pH-SA-D 50%

reactions Not relevant.

10.4. Conditions to avoid

Conditions to avoid Avoid exposure to high temperatures or direct sunlight.

Store in a well-ventilated area. Store in vessels suitable for

substances of low pH. Avoid contact with the

following materials: Strong alkalis. Strong oxidising

agents.

10.5. Incompatible materials

Materials to avoid Strong alkalis. Metals. Organics. Reacts violently with

water; ensure acid is always added to water, never the reverse. Avoid contact with sulphides, selenides or arsenic

compounds to prevent formation of the toxic gases

hydrogen sulphide, hydrogen selenide, or arsenous hydride.

10.6. Hazardous decomposition products

Hazardous decomposition

products Heating may generate the following products: Sulphurous

gases (SOx).

SECTION 11: Toxicology Information

11.1. Information on toxicological effects

Acute toxicity - oral

Acute toxicity oral (LD₅₀

mg/kg) 2,140.0 **Species** Rat

Acute toxicity - Inhalation

Species Rat

Inhalation Pulmonary oedema (excessive liquid in lungs) can occur

after inhalation of the higher amounts. Mist/droplets are corrosive to the respiratory tract, and will cause a burning sensation in the throat, coughing and breathing difficulties.

Long-term exposure may cause cancer of the larynx.

Skin contact Cause severe burns. May lead to permanent scarring.

Eye contact Risk of serious damage to eyes. Causes burns. Contact with

concentrated chemical may very rapidly cause eye damage,

possibly loss of sight.

SECTION 12: Ecological Information

12.1. Toxicity

Acute toxicity - Fish 48 hours: 49 mg/l, Lepomis macrochirus (Bluegill)

12.2. Persistence and degradability

Persistence and degradability Remains indefinitely in environment as sulphate.

12.3. Bioaccumulative potential

12.4. Mobility in soil

ClearFlo-pH-SA-D 50%

12.5. Results of PBT and vPvB assessment

12.6. Other adverse effects

Other adverse effects Release into drains will contribute to the acidification of

effluent treatment systems, and injure sewage treatment

organisms.

SECTION 13: Disposal considerations

13.1. Waste treatment methods

Disposal methods

Neutralise waste with alkaline material, such as crushed limestone, slaked lime (calcium hydroxide), soda ash (sodium carbonate) or sodium bicarbonate. Place waste in labelled, sealed containers. Dispose of waste via a licensed waste disposal contractor. Do not dispose directly into rivers or drains.

SECTION 14: Transport Information

14.1.UN number

UN no. (ADR/RID) 2769 UN no. (IMDG) 2796 UN no. (ICAO) 2796

14.2. UN proper shipping name

Proper shipping name

(ADR/RID) SULPHURIC ACID

14.3. Transport hazard class(es)

Transport labels



14.4. Packing group

ADR/RID packing group II
IMDG packing group II
ICAO packing group II

14.5. Environmental hazardous

Environmentally hazardous substance/marine pollutant No.

14.6. Special precautions for user

14.7. Transport in bulk according to Annex II of MARPOL and the IBC Code

SECTION 15: Regulatory Information

7 | Page

ClearFlo-pH-SA-D 50%

15.1. Safety, health and environmental regulations/legislation specific for the substance or

mixture

National regulations EH40/2005 Workplace exposure limits.

15.2. Chemical safety assessment

A chemical safety assessment has been carried out.

SECTION 16: Other Information

Revision comments This is the first issue using the GHS Pro software package.

Issue by GPC Clear Solutions Limited.

Revision date 22/09/2016

Revision 11

Supersedes date 11/06/2015

Risk phrases in full R35 Causes severe burns.

Hazard statements in full H314 Causes severe skin burns and eye damage.

This information relates only to the specific material designated and may not be valid for such material uses in combination with any other materials or in any process. Such information is, to the best of the company's knowledge and belief, accurate and reliable as of the date indicated. However, no warranty, guarantee or representation is made

Clear Flo-pH-SA-D~50% to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability of such information for his own particular use.